

1 Products affected:

Type / Part number	Description	Customer Part No.
4410.xxxx	T12-xxx (every Type of T12/TM12)	

2 Type of change :

Labeling change

3 Detailed description of change:

Label supplemented with: 50/60 Hz

4 Reason of change:

Claim of UL 1077

5 Released date:

	Batch Code
Production release	0823

6 Impact of change and recommended action:

Form: Changed information on part label
 Fit: N/A
 Function: N/A

7 Reference Documents / Attachments:

Kind of document	Document number	Remark
Notification change sheet	19382	Not attached

T12 - Label printed					0118.2003	
Created date:	Created by:	Released date:	Released by:	Notification-Nr.	Index	Page
16.01.2008 12:05:55	IST	06.03.2008	DSC	19382	-	1 of 1